


# 2010 FACILITIES ASSESSMENT SNOWDEN SCHOOL





## Project Data

<b>Location Code:</b>	092
<b>Address:</b>	1870 N. Parkway
<b>Year Built:</b>	1909
<b>Grade Configuration:</b>	K -8
<b>Student Capacity:</b>	
<b>Ideal Capacity:</b>	
<b>ADA Student Enrollment:</b>	
<b>Size:</b>	
<b>Portables:</b>	
<b>Building &amp; Addition</b>	


# 2010 FACILITIES ASSESSMENT SNOWDEN SCHOOL

<b>Description:</b>  Gymnasium windows are in poor working condition. The window system is very old.	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$95,000


<b>Description:</b>  Upgrade to ADA guidelines	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$110,000

<b>Description:</b>  Greenhouse in disrepair.	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$40,000


# 2010 FACILITIES ASSESSMENT SNOWDEN SCHOOL


<b>Description:</b> Stage floor is tiled.	
<b>Timeline:</b>  <b>TBD</b>	<b>Cost:</b>  <b>\$75,000</b>


<b>Description:</b> See previous item.	

<b>Description:</b> Replace bleachers and refinish floor	
<b>Timeline:</b>  <b>2010-11</b>	<b>Cost:</b>  <b>\$148,000</b>


2010 FACILITIES ASSESSMENT  
SNOWDEN SCHOOL

<b>Description:</b> Existing gym floor in poor condition	
<b>Timeline:</b>  <b>2010-00</b>	<b>Cost:</b>  <b>\$Included in previous cost w/bleachers</b>

<b>Description:</b> Brick mortar damaged / missing in several areas.	
<b>Timeline:</b>  <b>TBD</b>	<b>Cost:</b>  <b>\$32,000</b>

<b>Description:</b> Existing parking area in poor condition	
<b>Timeline:</b>  <b>TBD</b>	<b>Cost:</b>  <b>\$140,000</b>

# 2010 FACILITIES ASSESSMENT SNOWDEN SCHOOL


<b>Description:</b>  Existing concrete in poor condition.	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$20,000

<b>Description:</b>  Same as previous item	


<b>Description:</b>  Same as previous item	




2010 FACILITIES ASSESSMENT  
SNOWDEN SCHOOL

<b>Description:</b> Replace (2) chillers, boiler and pumps	
<b>Timeline:</b> 2015-16	<b>Cost:</b> \$1,120,000


<b>Description:</b> Install A/C in gymnasium	<b>Picture not available</b>
<b>Timeline:</b> 2012-13	<b>Cost:</b> \$212,000

<b>Description:</b> Replace gymnasium lighting	
<b>Timeline:</b> 2012-13	<b>Cost:</b> \$31,800


## 2010 FACILITIES ASSESSMENT SNOWDEN SCHOOL

<p><b>Description:</b></p> <p>Replace auditorium house lighting</p>	
<p><b>Timeline:</b></p> <p>2013-14</p>	<p><b>Cost:</b></p> <p>\$49,600</p>

<p><b>Description:</b></p> <p>Replace dimmer system</p>	<p style="text-align: center;">No picture available</p>
<p><b>Timeline:</b></p> <p>2011-12</p>	<p><b>Cost:</b></p> <p>\$87,400</p>

<p><b>Description:</b></p> <p>Intercom System</p> <p>Rauland MCZ300</p> <p>Installation Date: 1996</p>	
<p><b>Timeline:</b></p> <p>2010-11</p>	<p><b>Cost:</b></p> <p>\$70,000</p>

# 2010 FACILITIES ASSESSMENT SNOWDEN SCHOOL

<p><b>Description:</b></p> <p>PVC Single Ply roof: 10 years-fair</p> <p>PVC Single Ply roof: 1 year-good</p> <p>Slate roof: 20 years-poor</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost:</b></p> <p><b>\$588,266</b></p>