




2010 FACILITIES ASSESSMENT  
EAST CAREER & TECHNOLOGY CENTER





Project Data	
<b>Address:</b>	3206 Poplar
<b>Year Built:</b>	1976
<b>Grade Configuration:</b>	9-12
<b>Student Capacity:</b>	N/A
<b>Ideal Capacity:</b>	N/A
<b>ADA Student Enrollment:</b>	0
<b>Size:</b>	N/A
<b>Portables:</b>	0
<b>Building &amp; additions</b>	63,202 s. f.


## 2010 FACILITIES ASSESSMENT EAST CAREER & TECHNOLOGY CENTER

<p><b>Description:</b></p> <p>Ceiling tiles damaged in several locations.</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost</b></p> <p><b>Minimal</b></p>
<p><b>Description:</b></p> <p>Residual material (appears to be rust) on walls.</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost</b></p> <p><b>Unknown</b></p>
<p><b>Description:</b></p> <p>Dumpster has no enclosure.</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost</b></p> <p><b>\$5,000</b></p>

## 2010 FACILITIES ASSESSMENT EAST CAREER & TECHNOLOGY CENTER

<p><b>Description:</b></p> <p>Water ponding in parking area in front of shop doors.</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost</b></p> <p><b>\$4,000</b></p>

<p><b>Description:</b></p> <p>Replace clock/bell system</p>	
<p><b>Timeline:</b></p> <p><b>2016-17</b></p>	<p><b>Cost</b></p> <p><b>\$36,700</b></p>

<p><b>Description:</b></p> <p>PVS Single Ply roof: 6 years-fair</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost</b></p> <p><b>\$255,000</b></p>