




# 2010 FACILITIES ASSESSMENT AIRWAYS MIDDLE



Project Data	
<b>Location Code:</b>	123
<b>Address:</b>	2601 Ketchum
<b>Year Built:</b>	1968
<b>Grade Configuration:</b>	6-8
<b>Student Capacity:</b>	800
<b>Ideal Capacity:</b>	531
<b>ADA Student Enrollment:</b>	0
<b>Size:</b>	15 acres
<b>Portables:</b>	0
<b>Building &amp; Addition</b>	139,338 acres


# 2010 FACILITIES ASSESSMENT


## AIRWAYS MIDDLE


<p><b>Description:</b></p> <p>Upgrade to ADA guidelines</p>	
<p><b>Timeline:</b></p> <p>2012-13</p>	<p><b>Cost: 906,300</b></p>
<p><b>Description:</b></p> <p>Replace lighting throughout</p>	
<p><b>Timeline:</b></p> <p>2012-13</p>	<p><b>Cost:</b></p>
<p><b>Description:</b></p> <p>See previous item</p>	

# 2010 FACILITIES ASSESSMENT

## AIRWAYS MIDDLE


<b>Description:</b>  Pedestrian walkways are in poor condition.	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$40,000

<b>Description:</b>  No enclosure for Dumpsters (2).	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$10,000


<b>Description:</b>  Replace storefront windows	
<b>Timeline:</b>  2018-19	<b>Cost:</b>  \$247,800

# 2010 FACILITIES ASSESSMENT

## AIRWAYS MIDDLE


<p><b>Description:</b></p> <p>Patch, crack repair &amp; overlay 10,800 sq. yds. Of asphalt parking lot</p>	


<p><b>Description:</b></p> <p>See previous item.</p>	


<p><b>Description:</b></p> <p>Telecor CP-29 intercom</p>	
<p><b>Timeline:</b></p> <p><b>2011-12</b></p>	<p><b>Cost:</b></p> <p><b>\$96,720</b></p>

# 2010 FACILITIES ASSESSMENT

## AIRWAYS MIDDLE



<b>Description:</b> Replace HVAC controls	
<b>Timeline:</b> 2012-13	<b>Cost:</b> \$180,200

<b>Description:</b> Replace gymnasium lighting	
<b>Timeline:</b> 2012-13	<b>Cost:</b> \$33,920

<b>Description:</b> Replace auditorium house lighting	
<b>Timeline:</b> 2012-13	<b>Cost:</b> \$106,000

# 2010 FACILITIES ASSESSMENT

## AIRWAYS MIDDLE

<p><b>Description:</b></p> <p>Replace dimmer switch</p>	
<p><b>Timeline:</b></p> <p>2011-12</p>	<p><b>Costs:</b></p> <p>\$86,700</p>
<p><b>Description:</b></p> <p>PVC Single ply roof: 12 years-good</p>	
<p><b>Timeline:</b></p> <p>TBD</p>	<p><b>Costs:</b></p> <p>\$520,075</p>