



2010 FACILITIES ASSESSMENT CORDOVA HIGH




| Project Data | |
|---------------------------------|----------------|
| Location Code: | 106 |
| Address: | 1800 Berryhill |
| Year Built: | 1997 |
| Grade Configuration: | 9-12 |
| Student Capacity: | 1800 |
| Ideal Capacity: | 2350 |
| ADA Student Enrollment: | 0 |
| Size: | N/A |
| Portables: | 0 |
| Building & Addition: | 110,800 s. f. |

2010 FACILITIES ASSESSMENT CORDOVA HIGH


| | |
|--|--|
| Description: Existing gym bleachers are outdated, but in good condition overall. |  |
| Timeline: TBD | Cost: \$90,000 |


| | |
|---|---|
| Description: Replace gym lighting |  |
| Timeline: 2010-11 | Cost: \$41,000 |

| | |
|--|--|
| Description: Interior paint in fair to good condition. |  |
| Timeline: TBD | Cost: \$150,000 |


2010 FACILITIES ASSESSMENT CORDOVA HIGH

| | |
|--|--|
| Description: See previous item |  |
| | |


| | |
|--|---|
| Description: Fascia board around stadium press box is in poor condition. |  |
| Timeline: TBD | Cost: \$2,800 |

| | |
|---|--|
| Description: See previous item. |  |
| | |

2010 FACILITIES ASSESSMENT CORDOVA HIGH


| | |
|---|--|
| <p>Description:</p> <p>EPDM Single Ply with gravel roof: 18 years-poor</p> <p>Metal roof: 18 years</p> <p>Shingles on STD: 18 years-poor</p> |  |
| <p>Timeline:</p> <p>TBD</p> | <p>Cost:</p> <p>\$877,500</p> |

| | |
|--|---|
| <p>Description:</p> <p>Install A/C in gym</p> | <p style="text-align: center;">Picture not available</p> |
| <p>Timeline:</p> <p>2011-12</p> | <p>Cost:</p> <p>\$208,000</p> |

| | |
|--|--|
| <p>Description:</p> <p>Replace clock/bell system.</p> |  |
| <p>Timeline:</p> <p>2015-16</p> | <p>Cost:</p> <p>\$37,000</p> |

2010 FACILITIES ASSESSMENT CORDOVA HIGH

| | |
|---|---|
| <p>Description:</p> <p>Replace all HVAC Roof Top Units</p> | <p>Picture not available</p> |
| <p>Timeline:</p> <p>2010-11</p> | <p>Cost:</p> <p>\$1,901,547</p> |

| | |
|---|---|
| <p>Description:</p> <p>Intercom System: Telecor XL Installation Date: 1997</p> |  |
| <p>Timeline:</p> <p>TBD</p> | <p>Cost:</p> <p>\$90,000</p> |