

Walk-thru Metal Detectors

SERVICE REPAIR

Problem: The metal detector at Oakhaven High is displaying an error message "System Failure".

Tech Resolution: Opened the access door and unplugged both panel cables. - replaced the power cord also.

Problem: Calibrating issue at Georgian Hills

Resolution: Tech required

Problem: There appears to be something wrong with the sensor at Melrose High

Tech Resolution: Power cord was disconnected.

Problem: One of the walk-through metal detectors at A. Maceo Walker constantly beeps and may need to be recalibrated.

Tech Resolution: Provided the principle a demonstration on how to use the two units. They are working fine now.

Always check connections before placing a request for repair.

Technician:

Dennis Small
DVS Solutions, LLC
6094 Appletree Center, Suite 1
Memphis, TN 38115
Phone: (901) 205-9032
Fax: (901) 389-3589
Email: dennis@dvssllc.com
Cell: 901-205-9032