



2010 FACILITIES ASSESSMENT CORNING ELEMENTARY




Project Data	
Location Code:	124
Address:	1662 Dabbs
Year Built:	1968
Grade Configuration:	K-6
Student Capacity:	440/540
Ideal Capacity:	378
ADA Student Enrollment:	0
Size:	10.02 acres
Portables:	20
Building & Addition	50,954 s. f.



2010 FACILITIES ASSESSMENT CORNING ELEMENTARY

Description: Exterior needs paint and pressure washing.	
Timeline: TBD	Cost: \$33,000

Description: Same as previous item.	

Description: Upgrade to ADA guidelines	
Timeline: TBD	Cost: \$28,000

2010 FACILITIES ASSESSMENT CORNING ELEMENTARY

<p>Description:</p> <p>Intercom system</p> <p>Rauland 350</p> <p>Installation Date: 1998</p>	
<p>Timeline:</p> <p>2011-12</p>	<p>Cost:</p> <p>\$50,000</p>
<p>Description:</p> <p>Boiler is very old; however it is in good working condition. No Action required at the present time</p> <p>(Replacement in progress 3/10/2010)</p>	<p style="text-align: center;">No picture available</p>
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$26,000</p>
<p>Description:</p> <p>PVC Single Ply roof:</p> <p>9 years-fair</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$137,750</p>